

Survey

which were each 11 links distant instead of 17 links as recorded in Gov. field notes. Mr. M. H. Bushirk, my foreman having fixed this corner in two different surveys supposing the 17<sup>th</sup> were recorded by mistake and all the interested parties as named above agreeing that Mr. Bushirk's location of the corner should be taken as correct, I then commenced at the N.E. 1/4 mile post of sec. 14 T. 10 N., R. 2 W. ran three south with a variation of 32° to South 2 miles post of said sec. 14 coming out 63 links north and 5 links ~~east~~ if desired point (I ran south 78.58 ch.) I then corrected back one-fourth distance, ran three east 40 ch. missing the. I then located and established the N.E. corner of the S-8 quarter of the S-8 quarter of sec. 14 T. 10 N. R. 2 W. by planting a lime stone witnessed by two stones one being just 22 links, the other being N 35° E 10 links. I then found that the terminus of line last described was 33 links west and 1.38 E. North of corner just described. I then corrected back 1/4 distance located and established the N.W. corner of the S-8 quarter of the S-8 quarter of sec. 14 T. 10 N., Range 2 W. by planting a stone witnessed by two stones, one being planted S. 1 W. 35 links, the other N. 88° E. 28 1/2 links.

By consent of Mr. Squier, Shuburn and Stephan A. Elliott, Joseph B. Cosner acted as flagmen and Mr. William Cobb and Albert Cooksey acted as chain bearers in above survey, they each having been duly sworn.

I hereby certify the records of the above described surveys to be true.

In witness whereof I attach my hand and seal

A. G. Dillman

Morris Co. Surveyor.

